TP-Link Archer AX10 | AX1500 Wi-Fi 6

Warranty information (reference)

Independent product reference | English | 22 November 2026

How coverage is determined

• Warranty duration and terms depend on the country of purchase, seller, importer and regional TP-Link policy. No Iran-specific warranty period or issuer is verified here.

• Keep the original invoice, serial number and the product label showing hardware revision.

• For claims, contact the authorized seller or local TP-Link support and provide proof of purchase.

Typical limitations

• Damage due to incorrect power supplies, liquid exposure, physical misuse or unauthorized modifications may not be covered, subject to actual local terms.

• Do not treat this information sheet as a warranty certificate or evidence of entitlement.

Firmware and warranty

• TP-Link cautions that incorrect hardware-version or region firmware may damage the router and affect warranty coverage.

Sources and verification

https://www.tp-link.com/us/home-networking/wifi-router/archer-ax10/

https://www.tp-link.com/ae/support/download/archer-ax10/

https://static.tp-link.com/2019/201909/20190903/Archer%20AX10%28EU%26US%291.0_Datasheet.pdf

https://static.tp-link.com/upload/product-overview/2024/20240403/Archer%20AX10%203.0_Datasheet.pdf

This is an independently prepared reference document, NOT an official TP-Link publication, certificate, firmware file or warranty card. Hardware versions and regional specifications can differ.